

Vehicle Condition Report

Brasher's Portland Auto Auction

23585 NE Sandy Blvd.
Wood Village, OR 97060
(503) 492-9200

All listings are subject to change without notice. Information is deemed to be reliable, but not guaranteed until announced on the auction block.

Vehicle Description

2009 Dodge Dakota V8 Ext Cab Bighorn 4.7L

VIN	1D3HE32P29S785193		
Ext. Color	Gray		
Int. Color	Gray	Interior	Cloth
Mileage	43,362 Actual Miles		
Engine	4.7L 8-Cylinder Gas		
Transmission	Automatic		



Auction Data

Sale Date	Mon - Feb 8 - Open to the Public		
Run #	W013	Inv #	7172
Consignor	GSA FLEET SERVICES		

Declarations

Warranty	GSA Regular Terms
Mileage	43,362 Actual Miles
Title	Clear Title
Announcements	ENG ISSUES,RPRS MAYBE NEEDED,PRTS MAYBE MSNG

Equipment

- 2 Wheel Drive
- 4 Passenger
- Cruise Control
- AM/FM CD
- Power Brakes
- Automatic Transmission
- Power Windows
- Dual Air Bag
- Towing Package
- Electric Mirrors
- 8 Cylinder Gas
- Power Locks
- Alloy Wheels
- Hard Top
- Air Conditioning
- Trip Counter
- Tilt Steering Wheel
- Power Steering

Damage Descriptions (CR completed on 12/18/2015 by LUIS MEJIA)

#	Location	Damage Action	Severity	Parts \$	Other \$	Repair hours	Paint hours	Part hours	Total
Front									
1	Front Bumper	Chipped	Multiple Instances						--
									--
Front Subtotal				--	--	--	--	--	--
						--	--	--	--


Interior

2	Center Console	Worn	Acceptable						--
									--

2009 Dodge Dakota V8 Ext Cab Bighorn 4.7L

VIN: 1D3HE32P29S785193

Inv#: 7172

	#	Location	Damage Action	Severity	Parts \$	Other \$	Repair hours	Paint hours	Part hours	Total
	3	Left Front Seat	Torn	Multiple Instances						--
										--
	4	Left Rear Seat	Worn	Acceptable						--
										--
	5	Right Front Seat	Worn	Acceptable						--
										--
	6	Right Rear Seat	Worn	Acceptable						--
										--
	7	Steering Wheel	Worn	Acceptable						--
										--

Interior Subtotal

--	--	--	--	--	--
		--	--	--	--

Left

	8	Left Bed Side	Scratched	Multiple Instances						--
										--
	9	Left Front Door	Scratched	Multiple Instances						--
										--
	10	Left Front Door Panel	Worn	Acceptable						--
										--
	11	Left Front Fender	Light Scratch	Multiple Instances						--
										--
	12	Left Rear Door	Light Scratch	Multiple Instances						--
										--

Left Subtotal

--	--	--	--	--	--
		--	--	--	--

Mechanical

	13	Engine	Light On	Unknown						--
			Check and Advise							--
	14	Engine	Noise	Unknown						--
			Check and Advise							--

Comment: Leak/rough/knock

Mechanical Subtotal

--	--	--	--	--	--
		--	--	--	--

Rear

	15	Rear Bumper	Scratched	Multiple Instances						--
										--
	16	Tailgate	Light Scratch	Multiple Instances						--
										--

2009 Dodge Dakota V8 Ext Cab Bighorn 4.7L

VIN: 1D3HE32P29S785193

Inv#: 7172

Rear Subtotal

--	--	--	--	--	--
		--	--	--	--

Right

17	Right Bed Side	Dents W/No Pt. Dmg.	1 To 2 Inches	--
18	Right Front Door	Light Scratch	Multiple Instances	--
19	Right Front Door Panel	Worn	Acceptable	--
20	Right Rear Door	Light Scratch	Multiple Instances	--

Right Subtotal

--	--	--	--	--	--
		--	--	--	--

Total

--	--	--	--	--	--
		--	--	--	--

Tires

Region	Brand	Size	Tread Depth
Left Front	MATCHED	/-	Average (Average)
Left Rear	MATCHED	/-	Average (Average)
Right Front	MATCHED	/-	Average (Average)
Right Rear	MATCHED	/-	Average (Average)
Spare	FACTORY	/-	Average (Average)

Miscellaneous

Interior odor OK

Images



2009 Dodge Dakota V8 Ext Cab Bighorn 4.7L

VIN: 1D3HE32P29S785193

Inv#: 7172

